

## Release Note

**Product Name:** KDS-EN5, KDS-DEC5

<b>Current Version:</b>	Ver.Type	Ver No.	Date
	Firmware	5.10	March 2018
	Software	–	–
	Web	–	–
	Hardware	–	–

**RN Date:** March 2018

**Reference:** 12041

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
KDS-EN5	N/A	N/A	N/A
KDS-DEC5	N/A	N/A	N/A

### Technical Notes:

- This is a release note for new products.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Note

**Product Name:** KDS-EN5, KDS-DEC5

<b>Current Version:</b>	Ver.Type	Ver No.	Date
	Firmware	5.10	March 2018
	Software	–	–
	Web	–	–
	Hardware	–	–

**RN Date:** March 2018

**Reference:** 12041

This is a release note for new products. For a list of new product features see:

<http://www.kramerav.com/manual/KDS-EN5, KDS-DEC5>

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
12559	THD+N value is too low – R:-60dB.

### Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	None listed.

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)